Inspection Report

Name of Work	:	Providing JCB and Laboures for Lowering and Levelling the debries at Mallasandra Gutte in for 10 months in Ward No. 13, Mallasandra
Work Order	:	No. EE/PD/DZ/WO/ /2013-14 Date
Agency	:	K.R.I.D.L.
B.R. No. & Dated	:	
Bill Amount	:	Rs. 24,72,822
Job Code	:	013-14-000029
P. Code	:	P-1715
Date of Inspection	:	03-03-2016

The above said work "providing JCB and Laboures for Lowering and levelling the debris at Mallasandra Gutte in for 10 months in ward No 13 Mallasandra" was shown to me by the Concerned A.E

The work is inspected by me along with the Concerned Engineer and verified the records.

The work done is satisfactory

Ravi. N.C, AEW-12

Asst. Executive Engineer
Project Sub Division-I
Dasarahalli Zone,
Bruhat Bangalore Mahanagara Palike

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (PTD)
PUBLIC WORKS DEPARTMENT

Name of Work : Providing JCB and Laboures for Lowering and Levelling the debries at Mallasandra Gutte in for 10 months in Ward No. 13, Mallasandra

Asst. Executive Engineer
Project Sub Division-I
Dasarahalli Zone,
Bruhat Bengaluru Mahanagara Palike

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work : Providing JCB and Laboures for Lowering and Levelling the debries at Mallasandra Gutte in for 10 months in Ward No. 13, Mallasandra

Raees. N.K.
AE W-12

Asst. Executive Engineer
Project Sub Division-I
Dasarahalli Zone,
Bruhat Bengaluru Mahanagara Palike

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT